


WIRING DIAGRAM : PHASE FAILURE RELAY (PFR)

3Ø, 50Hz AC SUPPLY



NOTE 1: IT IS DESIRABLE TO DERIVE AUXILIARY VOLTAGES/SUPPLY USING SEPERATE AUXILIARY TRANSFORMER FROM MAINS, OF SUITABLE RATING.

NOTE 2: FOR SHUNT RELEASE CONNECT "C" & "N/O" CONTACTS FOR UV RELEASE OR CONTACTOR COIL CONNECT "C" & "N/C" CONTACTS SHOWING IN HEALTHY CONDITION