


**WIRING DIAGRAM : OVER LOAD / CURRENT RELAY**

**3Ø, 50Hz AC SUPPLY  
MAINS**



**RATED VOLTAGE FOR  
SHUNT TRIP COIL/UVR/OVR  
(FROM LOAD SIDE)**

**REAR VIEW OF O C S P L**

**NOTE 1: IT IS DESIRABLE TO DERIVE AUXILIARY VOLTAGES/SUPPLY USING  
SEPERATE AUXILIARY TRANSFORMER FROM MAINS, OF SUITABLE RATING.**

**NOTE 2: FOR SHUNT RELEASE CONNECT "C" & "N/O" CONTACTS  
FOR UV RELEASE OR CONTACTOR COIL CONNECT "C" & "N/C"  
CONTACTS SHOWING IN HEALTHY CONDITION**