


WIRING DIAGRAM: SOLID STATE VOLTAGE RELAY -VD 04

**1Ø, 50Hz AC SUPPLY
MAINS**



NOTE 1: IT IS DESIRABLE TO DERIVE AUXILIARY VOLTAGES/SUPPLY USING SEPARATE AUXILIARY TRANSFORMER FROM MAINS, OF SUITABLE RATING.

NOTE 2: FOR SHUNT RELEASE CONNECT "C" & "N/O" CONTACTS FOR UV RELEASE OR CONTACTOR COIL CONNECT "C" & "N/C" CONTACTS SHOWING IN HEALTHY CONDITION