


WIRING DIAGRAM :SOLID STATE VOLTAGE RELAY- VD SERIES

3Ø, 50Hz AC SUPPLY



NOTE 1: IT IS DESIRABLE TO DERIVE AUXILIARY VOLTAGES/SUPPLY USING SEPERATE AUXILIARY TRANSFORMER FROM MAINS, OF SUITABLE RATING.

**NOTE 2: FOR SHUNT RELEASE CONNECT "C" & "N/O" CONTACTS
FOR UV RELEASE OR CONTACTOR COIL CONNECT "C" & "N/C"
CONTACTS SHOWING IN HEALTHY CONDITION**