


WIRING DIAGRAM :TAP POSITION INDICATOR



NOTE 1: IT IS DESIRABLE TO DERIVE AUXILIARY VOLTAGES/SUPPLY USING SEPARATE AUXILIARY TRANSFORMER FROM MAINS, OF SUITABLE RATING.